

Whitley & Siddons * (512)477-9491 * Fax (512)481-1983 www.WhitleySiddons.com

4/9/2020 CAMERON 0331-04-069 PR 100 \$6,998,934|BRIDGE MAINTENANCE

| | eet | Title | _ (| eet Title | |
|----------|-----|--|--------------------|-------------------------|-----------------------|
| | 1 | TITLE SHEET | | 55 BRIDGE REPAIRS SHEET | ' 19 OF 30 |
| | 2 | INDEX OF SHEETS | | 56 BRIDGE REPAIRS SHEET | 20 OF 30 |
| | 3 | TYPICAL SECTIONS | | 57 BRIDGE REPAIRS SHEET | 21 OF 30 |
| r | 4 | GENERAL NOTES | | 58 BRIDGE REPAIRS SHEET | 22 OF 30 |
| | 4A | GENERAL NOTES | | 59 BRIDGE REPAIRS SHEET | 23 OF 30 |
| | 4B | GENERAL NOTES | | 60 BRIDGE REPAIRS SHEET | 24 OF 30 |
| 🗌 r | | ESTIMATE & QUANTITY | | 61 BRIDGE REPAIRS SHEET | |
| | | TCP SUMMARY SHEET SHEET 1 OF 2 | | 62 BRIDGE REPAIRS SHEET | |
| □r □r | | TCP SUMMARY SHEET SHEET 2 OF 2 | | 63 BRIDGE REPAIRS SHEET | |
| | | | | | |
| | | TRAFFIC CONTROL PLAN NOTES | _ | 64 BRIDGE REPAIRS SHEET | |
| | 9 | PHASE 1A TCP EB BRIDGE DECK REPAIRS & JOINT | | 65 BRIDGE REPAIRS SHEET | 29 OF 30 |
| | | REPLACEMENT | | 66 BRIDGE REPAIRS SHEET | 30 OF 30 |
| | 10 | PHASE 2A TCP EB BRIDGE DECK REPAIRS & JOINT | | 67 SLAB AND RAIL REPAIR | TABLES |
| | | REPLACEMENT | | 68 PRESTRESSED BEAM REP | AIR PLAN SHEET 1 OF 9 |
| | 11 | PHASE 3A TCP WB BRIDGE DECK REPAIRS & JOINT | | 69 PRESTRESSED BEAM REP | AIR PLAN SHEET 2 OF 9 |
| | | REPLACEMENT | | 70 PRESTRESSED BEAM REP | AIR PLAN SHEET 3 OF 9 |
| | 12 | PHASE 4A TCP WB BRIDGE DECK REPAIRS & JOINT | | 71 PRESTRESSED BEAM REP | AIR PLAN SHEET 4 OF 9 |
| _ | | REPLACEMENT | | 72 PRESTRESSED BEAM REP | |
| | | PHASE 1C TCP EB SURFACE TREATMENT | | 73 PRESTRESSED BEAM REP | |
| | | | | | |
| | | PHASE 2C TCP EB SURFACE TREATMENT | | 74 PRESTRESSED BEAM REP | |
| | | PHASE 3C TCP WB SURFACE TREATMENT | | 75 PRESTRESSED BEAM REP | |
| | 16 | PHASE 4C TCP WB SURFACE TREATMENT | | 76 PRESTRESSED BEAM REP | AIR PLAN SHEET 9 OF 9 |
| | 17 | PHASE 1B TCP EB MULTI LAYER POLYMER OVERLAY | | 77 MISCELLANEOUS REPAIR | DETAILS |
| | 18 | PHASE 2B TCP EB MULTI LAYER POLYMER OVERLAY | | 78 CONCRETE REPAIR SHEE | T 1 OF 13 78 |
| | 19 | PHASE 3B TCP WB MULTI LAYER POLYMER OVERLAY | | QIC_CONCRETE REPAIR- | 78 OLE1 |
| | 20 | PHASE 4B TCP WB MULTI LAYER POLYMER OVERLAY | | 79 CONCRETE REPAIR SHEE | T 2 OF 13 78 |
| | 21 | BC1-14 | | QIC_CONCRETE REPAIR- | 79 OLE1 |
| | 2.2 | BC2-14 | Πr | 80 CONCRETE REPAIR SHEE | |
| | | BC3-14 | | 81 CONCRETE REPAIR SHEE | |
| | | BC4-14 | Π_r | 82 CONCRETE REPAIR SHEE | |
| | | | □r | | |
| | | BC5-14 | = | 83 CONCRETE REPAIR SHEE | |
| | | BC6-14 | <u> </u> | 84 CONCRETE REPAIR SHEE | |
| | 27 | BC7-14 | _ r | 85 CONCRETE REPAIR SHEE | T 8 OF 13 |
| | 28 | BC8-14 | _ r | 86 CONCRETE REPAIR SHEE | T 9 OF 13 |
| | 29 | BC9-14 | r | 87 CONCRETE REPAIR SHEE | T 10 OF 13 |
| | 30 | BC10-14 | r | 88 CONCRETE REPAIR SHEE | T 11 OF 13 |
| | 31 | BC11-14 | r | 89 CONCRETE REPAIR SHEE | T 12 OF 13 |
| | 32 | BC12-14 | 🗌 r | 90 CONCRETE REPAIR SHEE | T 13 OF 13 |
| | 33 | TCP 2-5-18_MOD | r | 91 CONCRETE FRP CASING | SHEET 1 OF 3 |
| Π | | TCP 3-2 | $\overline{\Box}r$ | 92 CONCRETE FRP CASING | |
| r | | ESTIMATED QUANTITIES | \Box r | 93 CONCRETE FRP CASING | |
| | | BRIDGE TYPICAL SECTIONS | | 94 BULK CATHODIC PROTEC | |
| | | BRIDGE REPAIRS SHEET 1 OF 30 | | 95 BULK CATHODIC PROTEC | |
| | | BRIDGE REPAIRS SHEET 1 OF 30 BRIDGE REPAIRS SHEET 2 OF 30 | _ | 96 BULK CATHODIC PROTEC | |
| | | | _ | | |
| | | BRIDGE REPAIRS SHEET 3 OF 30 | r | 97 BULK CATHODIC PROTEC | |
| | | BRIDGE REPAIRS SHEET 4 OF 30 | = | 98 BULK CATHODIC PROTEC | |
| | | BRIDGE REPAIRS SHEET 5 OF 30 | r | 99 BULK CATHODIC PROTEC | |
| | 42 | BRIDGE REPAIRS SHEET 6 OF 30 | | 00 BULK CATHODIC PROTEC | |
| | 43 | BRIDGE REPAIRS SHEET 7 OF 30 | r | 01 BULK CATHODIC PROTEC | TION SHEET 8 OF 8 |
| | 44 | BRIDGE REPAIRS SHEET 8 OF 30 | r | 02 CP JACKET REPAIR SHE | ET 1 OF 2 |
| | 45 | BRIDGE REPAIRS SHEET 9 OF 30 | l r | 03 CP JACKET REPAIR SHE | ET 2 OF 2 |
| | 46 | BRIDGE REPAIRS SHEET 10 OF 30 | 🗌 r | 04 CP MONITORING SHEET | 1 OF 2 |
| | 47 | BRIDGE REPAIRS SHEET 11 OF 30 | | 05 CP MONITORING SHEET | |
| | | BRIDGE REPAIRS SHEET 12 OF 30 | | 06 STEEL SUPERSTRUCTURE | |
| | | | | 07 STEEL SUPERSTRUCTURE | |
| | | | = | | |
| | | BRIDGE REPAIRS SHEET 14 OF 30 | | 08 STEEL SUPERSTRUCTURE | |
| | | BRIDGE REPAIRS SHEET 15 OF 30 | | 09 STEEL SUPERSTRUCTURE | |
| | | BRIDGE REPAIRS SHEET 16 OF 30 | | 10 FENDER SYSTEM REPAIR | |
| | | BRIDGE REPAIRS SHEET 17 OF 30 | _ | 11 FENDER SYSTEM REPAIR | |
| | 54 | BRIDGE REPAIRS SHEET 18 OF 30 | L r | 12 FENDER SYSTEM REPAIR | . SHEET 3 OF 8 |
| | | | | | |

r = Revised Sheet



Whitley & Siddons * (512)477-9491 * Fax (512)481-1983 www.WhitleySiddons.com

4/9/2020 CAMERON 0331-04-069 PR 100 \$6,998,934|BRIDGE MAINTENANCE

| Sheet Title | | | | | | | |
|-------------|-----|-----------------------------------|--|--|--|--|--|
| 🗌 r | 113 | FENDER SYSTEM REPAIR SHEET 4 OF 8 | | | | | |
| 🗌 r | 114 | FENDER SYSTEM REPAIR SHEET 5 OF 8 | | | | | |
| 🗌 r | 115 | FENDER SYSTEM REPAIR SHEET 6 OF 8 | | | | | |
| 🗌 r | 116 | FENDER SYSTEM REPAIR SHEET 7 OF 8 | | | | | |
| 🗌 r | 117 | FENDER SYSTEM REPAIR SHEET 8 OF 8 | | | | | |
| | 118 | SEJ-M | | | | | |
| | 119 | EB INSIDE LANE PAVEMENT MARKINGS | | | | | |
| | 120 | EB OUTSIDE LANE PAVEMENT MARKINGS | | | | | |
| | 121 | WB OUTSIDE LANE PAVEMENT MARKINGS | | | | | |
| | 122 | WB INSIDE LANE PAVEMENT MARKINGS | | | | | |
| | 123 | PM1-12 | | | | | |
| | 124 | PM2-12 | | | | | |
| | 125 | CPM1-14 | | | | | |
| | 126 | EPIC SHEET 1 OF 2 | | | | | |
| | 127 | EPIC SHEET 2 OF 2 | | | | | |
| | 128 | EPIC TPWD BMPS SHEET 1 OF 3 | | | | | |
| | 129 | EPIC TPWD BMPS SHEET 2 OF 3 | | | | | |
| | 130 | EPIC TPWD BMPS SHEET 3 OF 3 | | | | | |
| l r | 131 | TXDOT SW3P | | | | | |
| | 132 | EC1-16 | | | | | |
| | 133 | EC2-16 | | | | | |
| | 134 | EC3-16 | | | | | |
| | 135 | TECL-17 PHR | | | | | |
| | | | | | | | |

Sheet Title