**Whitley & Siddons * (512)477-9491 * Fax (512)481-1983**
**www.WhitleySiddons.com**

**11/3/2017 RED RIVER 0427-02-009 FM 1158 $2,703,451|REHABILITATION OF EXISTING ROAD**


| | Sheet | Title |
|---|---|---|
| ☐ | 1 | TITLE SHEET |
| ☐ | 2 | INDEX OF SHEETS |
| ☐ | 3 | TYPICAL SECTION |
| ☐ | 4 | PAVEMENT CORE DATA |
| ☐ | 5 | GENERAL NOTES |
| ☐ | 5A | GENERAL NOTES |
| ☐ | 5B | GENERAL NOTES |
| ☐ | 5C | GENERAL NOTES |
| ☐r | 5D | GENERAL NOTES |
| ☐ | 5E | GENERAL NOTES |
| ☐r | 7 | ESTIMATE & QUANTITY SHEET |
| ☐r | 7A | ESTIMATE & QUANTITY SHEET |
| ☐ | 8 | QUANTITY SUMMARIES |
| ☐r | 9 | QUANTITY SUMMARIES |
| ☐ | 10 | QUANTITY SUMMARIES |
| ☐r | 11 | QUANTITY SUMMARIES |
| ☐r | 12 | SEQUENCE OF WORK |
| ☐ | 13 | BC1-14 |
| ☐ | 14 | BC2-14 |
| ☐ | 15 | BC3-14 |
| ☐ | 16 | BC4-14 |
| ☐ | 17 | BC5-14 |
| ☐ | 18 | BC6-14 |
| ☐ | 19 | BC7-14 |
| ☐ | 20 | BC8-14 |
| ☐ | 21 | BC9-14 |
| ☐ | 22 | BC10-14 |
| ☐ | 23 | BC11-14 |
| ☐ | 24 | BC12-14 |
| ☐ | 25 | TREATMENT FOR VARIOUS EDGE CONDITIONS |
| ☐ | 26 | TCP1-1-12 |
| ☐ | 27 | TCP1-2-12 |
| ☐ | 28 | TCP2-1-12 |
| ☐ | 29 | TCP2-2-12 |
| ☐ | 30 | TCP2-8-12 |
| ☐ | 31 | TCP3-1-13 |
| ☐ | 32 | TCP3-3-14 |
| ☐ | 33 | WZRS-16 |
| ☐ | 34 | WZSTPM-13 |
| ☐ | 35 | WZUL-13 |
| ☐ | 36 | PLAN LAYOUT |
| ☐ | 37 | PLAN LAYOUT |
| ☐ | 38 | PLAN LAYOUT |
| ☐ | 39 | PLAN LAYOUT |
| ☐ | 40 | PLAN LAYOUT |
| ☐ | 41 | PLAN LAYOUT |
| ☐ | 42 | PLAN LAYOUT |
| ☐ | 43 | PLAN LAYOUT |
| ☐ | 44 | SUPERELEVATION TABLE |
| ☐ | 45 | INTERSECTION & DRIVEWAY DETAILS |
| ☐ | 46 | TREE TRIMMING AND BUSH REMOVAL |
| ☐ | 47 | MAILBOX TURNOUT DETAILS |
| ☐ | 48 | MISC DETAILS |
| ☐ | 49 | MB-151 |
| ☐ | 50 | MB-151 |
| ☐ | 51 | MB-151 |
| ☐ | 52 | MB-151 |
| ☐ | 53 | HYDRAULIC DATA |
| ☐ | 54 | HYDRAULIC DATA |
| ☐ | 55 | CROSS CULVERTS STA 0+57 |
| ☐ | 56 | CROSS CULVERTS STA 10+53 |
| ☐ | 57 | CROSS CULVERTS STA 17+44 |
| ☐ | 58 | CROSS CULVERTS STA 35+94 |
| ☐ | 59 | CROSS CULVERTS STA 83+44 |
| ☐ | 60 | CROSS CULVERTS STA 102+41 |
| ☐ | 61 | CROSS CULVERTS STA 117+36 |
| ☐ | 62 | CROSS CULVERTS STA 138+87 |
| ☐ | 63 | CROSS CULVERTS STA 150+75 |
| ☐ | 64 | CROSS CULVERTS STA 157+83 |
| ☐ | 65 | CROSS CULVERTS STA 165+82 |
| ☐ | 66 | CROSS CULVERTS STA 170+96 |
| ☐ | 67 | CROSS CULVERTS STA 184+64 |
| ☐ | 68 | BCS |
| ☐ | 69 | ECD |
| ☐ | 70 | PSET-SC |
| ☐ | 71 | PSET-SP |
| ☐ | 72 | PW |
| ☐ | 73 | SETB-FW-0 |
| ☐ | 74 | SETB-FW-0 |
| ☐ | 75 | SETB-FW-0 |
| ☐ | 79 | SETBR |
| ☐ | 80 | SCC-5 & 6 |
| ☐ | 81 | SCC-5 & 6 |
| ☐ | 82 | SCC-7 |
| ☐ | 83 | SCC-7 |
| ☐ | 84 | SCC-MD |
| ☐ | 85 | MC-8-13 |
| ☐ | 86 | MC-8-13 |
| ☐ | 87 | MC-MD |
| ☐ | 88 | SETP-CD |
| ☐ | 89 | SETP-CD |
| ☐ | 90 | SETP-PD |
| ☐r | 91 | SMALL SIGN SUMMARY |
| ☐r | 92 | SMALL SIGN SUMMARY |
| ☐r | 93 | SMALL SIGN SUMMARY |
| ☐ | 94 | SIGN DETAIL |
| ☐ | 95 | SMDGEN-08 |
| ☐ | 96 | SMDSLIP-1-08 |
| ☐ | 97 | SMDSLIP-2-08 |
| ☐ | 98 | SMDSLIP-3-08 |
| ☐ | 99 | SMDTWT-08 |
| ☐ | 100 | TSR3-13 |
| ☐ | 101 | TSR4-13 |
| ☐ | 102 | TSR5-13 |
| ☐ | 103 | D & OM1-15 |
| ☐ | 104 | D & OM2-15 |
| ☐ | 105 | D & OM3-15B |
| ☐ | 106 | D & OM4-15 |
| ☐ | 107 | PM1-12 |
| ☐ | 108 | PM2-12 |
| ☐ | 109 | SW3P |
| ☐ | 110 | EPIC |
| ☐ | 111 | LAYOUT OF EROSION CONTROL MEASURES |
| ☐ | 112 | LAYOUT OF EROSION CONTROL MEASURES |
| ☐ | 113 | LAYOUT OF EROSION CONTROL MEASURES |
| ☐ | 114 | LAYOUT OF EROSION CONTROL MEASURES |
| ☐ | 115 | LAYOUT OF EROSION CONTROL MEASURES |
| ☐ | 116 | LAYOUT OF EROSION CONTROL MEASURES |
| ☐ | 117 | LAYOUT OF EROSION CONTROL MEASURES |
| ☐ | 118 | LAYOUT OF EROSION CONTROL MEASURES |


**r = Revised Sheet**

**Total Sheets in Plan Set: 122**

**Whitley & Siddons * (512)477-9491 * Fax (512)481-1983**
**www.WhitleySiddons.com**

**11/3/2017 RED RIVER 0427-02-009 FM 1158 $2,703,451|REHABILITATION OF EXISTING ROAD**

| | Sheet | Title |
|---|---|---|
| ☐ | 119 | EC1-16 |
| ☐ | 120 | EC2-16 |

| Sheet | Title |
|---|---|

r = Revised Sheet

**Total Sheets in Plan Set: 122**