Whitley & Siddons * (512)477-9491 * Fax (512)481-1983
www.WhitleySiddons.com

5/2/2018 WILLIAMSON 1566-01-011 FM 1660 $2,430,755|DEPTH REPAIR, UNDERSEAL & THIN OV

Sheet	Title
1	TITLE SHEET
2	INDEX OF SHEETS
3	TYPICAL SECTIONS
4	TYPICAL SECTIONS
5	MISCELLANEOUS DETAILS
6	MISCELLANEOUS DETAILS
6A	BRIDGE JOINT DETAILS
7	PAVING LIMITS DETAILS
8	GENERAL NOTES
8A	GENERAL NOTES
8B	GENERAL NOTES
8C	GENERAL NOTES
8D	GENERAL NOTES
8E	GENERAL NOTES
9	ESTIMATE AND QUANTITY
9A	ESTIMATE AND QUANTITY
10	QUANTITY SUMMARY
11	QUANTITY SUMMARY
12	SEQUENCE OF CONSTRUCTION
13	BC1-14
14	BC2-14
15	BC3-14
16	BC4-14
17	BC5-14
18	BC6-14
19	BC7-14
20	BC8-14
21	BC9-14
22	BC10-14
23	BC11-14
24	BC12-14
25	TCP2-2-18
26	TCP3-1-13
27	TCP3-3-14
28	WZTD-17
29	WZSTPM-13
30	WZUL-13
31	WZRCD-13
32	WZBTS-1-13
33	WZBTS-2-13
34	WZBRK-13
35	WZRS-16
36	TEHMAC-11
37	GF31-14
38	GF31TR-14
39	T202 TRANSITION RETROFIT GUIDE MOD
40	BED-14
41	SGT8-17
41A	SGT8S31-17
41B	SGT10S31-16
41C	SGT11S31-18
42	ED1-14
43	ED4-14
44	LD1-03
45	LD2-03
46	PM1-12
47	PM2-12
48	PM3-12
49	RS3-13
50	RS4-13
51	RS5-13
52	ENVIRONMENTAL PERMIT, ISSUES AND COMMITMENTS
53	EC1-16

r = Revised Sheet

Total Sheets in Plan Set: 63