Whitley & Siddons * (512)477-9491 * Fax (512)481-1983
www.WhitleySiddons.com

5/8/2019 OLDHAM 0090-09-006 BI 40-- $5,959,636|2018 BMIP REPAIR BRIDGE

Sheet	Title
1	TITLE SHEET
2	INDEX OF SHEETS
3	TYPICAL SECTIONS BI 40 AT IH 40
4	TYPICAL SECTIONS FM 2161 AT IH 40
5	GENERAL NOTES
5A	GENERAL NOTES
5B	GENERAL NOTES
5C	GENERAL NOTES
5D	GENERAL NOTES
5E	GENERAL NOTES
5F	GENERAL NOTES
5G	GENERAL NOTES
5H	GENERAL NOTES
6	ESTIMATE AND QUANTITY
6A	ESTIMATE AND QUANTITY
7	QUANTITY SUMMARIES REMOVAL, ROADWAY, EARTHWORK AND EROSION CONTROL
8	QUANTITY SUMMARIES TCP, DETOUR AND SIGNING AND STRIPING
9	CONSTRUCTION NARRATIVE
10	DETOUR SIGNING LAYOUT - FM 2161 CLOSURE
11	DETOUR SIGNING LAYOUT - EB IH 40 CLOSURE AT FM 2161
12	DETOUR SIGNING LAYOUT - WB IH 40 CLOSURE AT FM 2161
13	DETOUR SIGNING LAYOUT - BI 40 BRIDGE CLOSURE
14	TRAFFIC CONTROL PLAN - IH 40 AT FM 2161
15	DETOUR TYPICAL SECTIONS
16	TRAFFIC CONTROL PLANS - DETOUR NO. 1
17	TRAFFIC CONTROL PLANS - DETOUR NO. 2
18	TRAFFIC CONTROL PLANS - EB MAINLINE CLOSURE BI 40 BRIDGE SHEET 1 OF 5
19	TRAFFIC CONTROL PLANS - EB MAINLINE CLOSURE BI 40 BRIDGE SHEET 2 OF 5
20	TRAFFIC CONTROL PLANS - EB MAINLINE CLOSURE BI 40 BRIDGE SHEET 3 OF 5
21	TRAFFIC CONTROL PLANS - EB MAINLINE CLOSURE BI 40 BRIDGE SHEET 4 OF 5
22	TRAFFIC CONTROL PLANS - EB MAINLINE CLOSURE BI 40 BRIDGE SHEET 5 OF 5
23	TRAFFIC CONTROL PLANS - WB MAINLINE CLOSURE BI 40 BRIDGE SHEET 1 OF 5
24	TRAFFIC CONTROL PLANS - WB MAINLINE CLOSURE BI 40 BRIDGE SHEET 2 OF 5
25	TRAFFIC CONTROL PLANS - WB MAINLINE CLOSURE BI 40 BRIDGE SHEET 3 OF 5
26	TRAFFIC CONTROL PLANS - WB MAINLINE CLOSURE BI 40 BRIDGE SHEET 4 OF 5
27	TRAFFIC CONTROL PLANS - WB MAINLINE CLOSURE BI 40 BRIDGE SHEET 5 OF 5
28	BC1-14
29	BC2-14
30	BC3-14
31	BC4-14
32	BC5-14
33	BC6-14
34	BC7-14
35	BC8-14
36	BC9-14
37	BC10-14

Sheet	Title
38	BC11-14
39	BC12-14
40	SLED-14
41	TCP1-5-18
42	TCP2-6-18
43	TCP3-1-13
44	TCP3-2-13
45	TCP3-3-14
46	TCP5-1-18
47	TCP6-1-12
48	TCP6-2-12
49	TCP6-3-12
50	TCP6-4-12
51	TCP6-5-12
52	TCP6-6-12
53	TCP6-7-12
54	TCP7-1-13
55	WZRCD-13
56	WZRS-16
57	WZTD-17
58	HORIZONTAL ALIGNMENT DATA SHEET 1 OF 2
59	HORIZONTAL ALIGNMENT DATA SHEET 2 OF 2
60	HORIZONTAL AND VERTICAL CONTROL - BI-40 SHEET 1 OF 4
61	HORIZONTAL AND VERTICAL CONTROL - BI-40 SHEET 2 OF 4
62	HORIZONTAL AND VERTICAL CONTROL - BI-40 SHEET 3 OF 4
63	HORIZONTAL AND VERTICAL CONTROL - BI-40 SHEET 4 OF 4
64	HORIZONTAL AND VERTICAL CONTROL - FM 2161 SHEET 1 OF 4
65	HORIZONTAL AND VERTICAL CONTROL - FM 2161 SHEET 2 OF 4
66	HORIZONTAL AND VERTICAL CONTROL - FM 2161 SHEET 3 OF 4
67	HORIZONTAL AND VERTICAL CONTROL - FM 2161 SHEET 4 OF 4
68	BI-40 ROADWAY PLAN & PROFILE SHEET 1 OF 2
69	BI-40 ROADWAY PLAN & PROFILE SHEET 2 OF 2
70	FM 2161 ROADWAY PLAN & PROFILE
71	GF31-14
72	GF31TR-14
73	GF31MS-17
74	BED-14
75	SGT10S31-16
76	SGT12S31-18
77	TAU-IIN-16
78	TRF
79	QUADN-17
80	CRASH CUSHION SUMMARY SHEET
81	BRIDGE LAYOUT BI-40 UNDERPASS
82	TYPICAL SECTIONS BI-40 UNDERPASS
83	ESTIMATED QUANTITIES BI-40 UNDERPASS
84	ABUTMENT BACKWALL & WINGWALL REMOVAL BI-40 UNDERPASS SHEET 1 OF 2
85	ABUTMENT BACKWALL & WINGWALL REMOVAL BI-40 UNDERPASS SHEET 2 OF 2
86	ABUTMENT BACKWALL & WINGWALL RECONSTRUCTION DETAILS BI-40 UNDERPASS SHEET 1 OF 3

r = Revised Sheet

Total Sheets in Plan Set: 158

Whitley & Siddons * (512)477-9491 * Fax (512)481-1983
www.WhitleySiddons.com

5/8/2019 OLDHAM 0090-09-006 BI 40-- $5,959,636|2018 BMIP REPAIR BRIDGE

Sheet	Title
87	ABUTMENT BACKWALL & WINGWALL RECONSTRUCTION DETAILS BI-40 UNDERPASS SHEET 2 OF 3
88	ABUTMENT BACKWALL & WINGWALL RECONSTRUCTION DETAILS BI-40 UNDERPASS SHEET 3 OF 3
89	ABUTMENT REPAIR DETAILS BI-40 UNDERPASS
90	BENT NO. 2 REPAIR DETAILS BI-40 UNDERPASS
91	BENT NO. 3 REPAIR DETAILS BI-40 UNDERPASS
92	BENT NO. 4 REPAIR DETAILS BI-40 UNDERPASS
93	BRIDGE RAISING DETAILS & BEAM REPAIR SUMMARY BI-40 UNDERPASS
94	STEEL PEDESTAL DETAILS BI-40 UNDERPASS
95	BEARING DETAILS BI-40 UNDERPASS
96	SLAB RECONSTRUCTION DETAILS BI-40 UNDERPASS SHEET 1 OF 2
97	SLAB RECONSTRUCTION DETAILS BI-40 UNDERPASS SHEET 2 OF 2
98	BRIDGE LAYOUT FM 2161 OVERPASS
99	TYPICAL SECTION FM 2161 OVERPASS.PD
100	ESTIMATED QUANTITIES FM 2161 OVERPASS
101	ABUTMENT BACKWALL & WINGWALL REMOVAL DETAILS FM 2161 OVERPASS
102	ABUTMENT BACKWALL & WINGWALL RECONSTRUCTION DETAILS FM 2161 OVERPASS
103	ABUTMENT AND BEAM REPAIR DETAILS FM 2161 OVERPASS
104	SHORING DETAILS FM 2161 OVERPASS
105	SLAB REMOVAL DETAILS FM 2161 OVERPASS SHEET 1 OF 2
106	SLAB REMOVAL DETAILS FM 2161 OVERPASS SHEET 2 OF 2
107	SLAB RECONSTRUCTION DETAILS FM 2161 OVERPASS SHEET 1 OF 2
108	SLAB RECONSTRUCTION DETAILS FM 2161 OVERPASS SHEET 2 OF 2
109	HEADER JOINT DETAILS
110	BAS-A
111	CSAB
112	CRR
113	MEBRC SHEET 1 OF 2
114	MEBRC SHEET 2 OF 2
115	PMDF SHEET 1 OF 2
116	PMDF SHEET 2 OF 2
117	SSTR SHEET 1 OF 2
118	SSTR SHEET 2 OF 2
119	SUMMARY OF SMALL SIGNS
120	SIGNING AND STRIPING PLANS BI-40
121	SIGNING AND STRIPING PLANS IH-40 MAINLANE SHEET 1 OF 5
122	SIGNING AND STRIPING PLANS IH-40 MAINLANE SHEET 2 OF 5
123	SIGNING AND STRIPING PLANS IH-40 MAINLANE SHEET 3 OF 5
124	SIGNING AND STRIPING PLANS IH-40 MAINLANE SHEET 4 OF 5
125	SIGNING AND STRIPING PLANS IH-40 MAINLANE SHEET 5 OF 5
126	SIGNING AND STRIPING PLANS FM 2161
127	D&OM1-15
128	D&OM2-15
129	D&OM3-15B
130	D&OM5-15
131	D&OMVIA-15
132	SMDGEN-08
133	SMDSLIP-1-08
134	SMDSLIP-2-08
135	SMDSLIP-3-08
136	TSR4-13
137	PM1-12
138	PM2-12
139	PM4-12
140	CPM1-14
141	TXDOT STORM WATER POLLUTION PREVENTION PLAN SW3P
142	EPIC
143	SW3P PLANS BI-40
144	SW3P PLANS FM 2161
145	EC1-16
145	EC9-16 SHEET 1 OF 3
146	EC9-16 SHEET 2 OF 3
147	EC9-16 SHEET 3 OF 3
149	VEGETATION SPECIFICATION SHEET

r = Revised Sheet

Total Sheets in Plan Set: 158