Whitley & Siddons * (512)477-9491 * Fax (512)481-1983
www.WhitleySiddons.com

4/8/2020 OLDHAM 0090-02-053 IH 40 $4,469,165|IMPROVE GUARDRAIL TO DESIGN STANDARDS

Sheet	Title
1	TITLE SHEET
2	INDEX OF SHEETS
3	LOCATION MAP
4	GENERAL NOTES
4A	GENERAL NOTES
4B	GENERAL NOTES
5	ESTIMATE & QUANTITY SUMMARY
5A	ESTIMATE & QUANTITY SUMMARY
5B	ESTIMATE & QUANTITY SUMMARY
5C	ESTIMATE & QUANTITY SUMMARY
6	PROJECT SUMMARY
7	PROJECT SUMMARY
8	PROJECT SUMMARY
9	PROJECT SUMMARY
10	TRAFFIC CONTROL LAYOUT
11	TRAFFIC CONTROL LAYOUT
12	TRAFFIC CONTROL LAYOUT
13	TRAFFIC CONTROL LAYOUT
14	BC 1-14
15	BC 2-14
16	BC 3-14
17	BC 4-14
18	BC 5-14
19	BC 6-14
20	BC 7-14
21	BC 8-14
22	BC 9-14
23	BC 10-14
24	BC 11-14
25	BC 12-14
26	TCP 1-1-18
27	TCP 1-2-18
28	TCP 1-5-18
29	TCP 1-6-18
30	TCP 2-1-18
31	TCP 2-2-18
32	TCP 2-6-18
33	TCP 3-1-13 TCP 3-1-13
34	TCP 3-2-13
35	TCP 3-4-13 TCP 3-4-13
36	TCP 5-1-18
37	TCP 6-1-12
38	TCP 6-2-12
39	TCP 6-3-12
40	TCP 6-4-12
41	TCP 6-5-12
42	WZ RS-16
43	WZ TD-17
44	ABSORBM-19
45	SLED-14
46	MBGF LAYOUT
47	MBGF LAYOUT
48	MBGF LAYOUT
49	MBGF LAYOUT
50	MBGF LAYOUT
51	MBGF LAYOUT
52	MBGF LAYOUT
53	MBGF LAYOUT
54	MBGF LAYOUT
55	MBGF LAYOUT
56	MBGF LAYOUT
57	MBGF LAYOUT
58	MBGF LAYOUT
59	MBGF LAYOUT
60	MBGF LAYOUT
61	MBGF LAYOUT
62	MBGF LAYOUT
63	MBGF LAYOUT
64	MBGF LAYOUT
65	MBGF LAYOUT
66	MBGF LAYOUT
67	MBGF LAYOUT
68	MBGF LAYOUT
69	MBGF LAYOUT
70	MBGF LAYOUT
71	MBGF LAYOUT
72	BED-14
73	CRASH CUSHION SUMMARY SHEET
74	GF 31 DAT-19
75	GF 31 MS-19
76	GF 31 T101-19
77	GF 31 TR TL3-19
78	GF 31 TR TL3-19
79	GF 31-19
80	SGT 10S 31-16
81	SGT 12S 31-18
82	SMTC N-16
83	SSCB 1F-10
84	SSCB 3-10
85	DRAINAGE DETAILS
86	DRAINAGE DETAILS
87	SCC-MD
88	SETP-PD
89	SP
89A	PSET-RR PSET-RR
90	BRIDGE REPAIR AND RAIL RETROFIT LAYOUT - EB IH 40 OVERPASS AT WILDORADO FM 809
91	BRIDGE REPAIR AND RAIL RETROFIT LAYOUT - WB IH 40 OVERPASS AT WILDORADO FM 809
92	BRIDGE REPAIR AND RAIL RETROFIT LAYOUT - EB IH 40 OVERPASS AT US 385
93	BRIDGE REPAIR AND RAIL RETROFIT LAYOUT - WB IH 40 OVERPASS AT US 385
94	EXISTING STRUCTURE PHOTOS - EB IH 40 OVERPASS AT WILDORADO FM 809
95	EXISTING STRUCTURE PHOTOS - WB IH 40 OVERPASS AT WILDORADO FM 809
96	EXISTING STRUCTURE PHOTOS - EB IH 40 OVERPASS AT US 385
97	EXISTING STRUCTURE PHOTOS - WB IH 40 OVERPASS AT US 385
98	EXISTING STRUCTURE PHOTOS - WB IH 40 OVERPASS AT US 385
99	TYPE SSTR RAIL RETROFIT
100	TYPE SSTR RAIL RETROFIT
101	TRAFFIC RAIL SINGLE SLOPE TYPE SSTR
102	TRAFFIC RAIL SINGLE SLOPE TYPE SSTR
103	CPM 1-14
104	D&OM 1-15
105	D&OM 2-15

r = Revised Sheet

Total Sheets in Plan Set: 119

Whitley & Siddons * (512)477-9491 * Fax (512)481-1983
www.WhitleySiddons.com

4/8/2020 OLDHAM 0090-02-053 IH 40 $4,469,165|IMPROVE GUARDRAIL TO DESIGN STANDARDS

	Sheet	Title
☐	106	D&OM 5-15
☐	107	D&OM 6-15
☐	108	D&OM VIA-15
☐	109	PM 1-12
☐	110	EPIC
☐	111	SW3P SW3P
☐	112	SW3P LAYOUT
☐	113	VEGETATION SPECIFICATION SHEET

Sheet Title

r = Revised Sheet

Total Sheets in Plan Set: 119