



Whitley & Siddons * (512)477-9491 * Fax (512)481-1983

www.WhitleySiddons.com

1/9/2019 CARSON 0275-04-052 IH 40 \$7,990,543|ACP OVERLAY,CRCP REPAIR, MBGF, AND STRIPING.

Sheet Title

- ☐ 1 TITLE SHEET
- ☐ 2 INDEX OF SHEETS
- ☐ 3 TYPICAL SECTIONS
- ☐ 4 GENERAL NOTES
- ☐ 4A GENERAL NOTES
- ☐ 4B GENERAL NOTES
- ☐ 4C GENERAL NOTES
- ☐ 5 ESTIMATE & QUANTITY
- ☐ 6 PROJECT SUMMARY
- ☐ 7 PROJECT SUMMARY
- ☐ 8 BC 1-14
- ☐ 9 BC 2-14
- ☐ 10 BC 3-14
- ☐ 11 BC 4-14
- ☐ 12 BC 5-14
- ☐ 13 BC 6-14
- ☐ 14 BC 7-14
- ☐ 15 BC 8-14
- ☐ 16 BC 9-14
- ☐ 17 BC 10-14
- ☐ 18 BC 11-14
- ☐ 19 BC 12-14
- ☐ 20 TCP 1-4-18
- ☐ 21 TCP 1-5-18
- ☐ 22 TCP 2-5-18
- ☐ 23 TCP 2-6-18
- ☐ 24 TCP 3-1-13
- ☐ 25 TCP 3-2-13
- ☐ 26 TCP 3-3-14
- ☐ 27 TCP 5-1-18
- ☐ 28 TCP 6-1-12
- ☐ 29 TCP 6-2-12
- ☐ 30 TCP 6-3-12
- ☐ 31 TCP 6-4-12
- ☐ 32 TCP 6-5-12
- ☐ 33 WZ RS-16
- ☐ 34 WZ STPM-13
- ☐ 35 WZ TD-17
- ☐ 36 WZ UL-13
- ☐ 37 ADDITIONAL AREAS
- ☐ 38 ADDITIONAL AREAS
- ☐ 39 ADDITIONAL AREAS
- ☐ 40 ADDITIONAL AREAS
- ☐ 41 ADDITIONAL AREAS
- ☐ 42 ADDITIONAL AREAS
- ☐ 43 CONCRETE REPAIR
- ☐ 44 MBGF LAYOUT
- ☐ 45 APPROACH SLAB JOINT REPAIR DETAILS
- ☐ 46 BRIDGE JOINT REPAIR DETAILS
- ☐ 47 T202TR
- ☐ 48 CRCP1-17
- ☐ 49 CRCP1-17
- ☐ 50 GF31-14
- ☐ 51 GF31DAT-14
- ☐ 52 GF 31 TR-14
- ☐ 53 SGT10S31-16
- ☐ 54 SGT12S31-18
- ☐ 55 TEHMAC-11
- ☐ 56 TYPICAL PAVEMENT MARKING LAYOUT
- ☐ 57 D&OM1-15

Sheet Title

- ☐ 58 D&OM2-15
- ☐ 59 D&OM3-15B
- ☐ 60 D&OM4-15
- ☐ 61 D&OM6-15
- ☐ 62 D&OMVIA-15
- ☐ 63 PM1-12
- ☐ 64 PM2-12
- ☐ 65 PM3-12
- ☐ 66 PM4-12
- ☐ 67 RS1-13
- ☐ 68 EPIC EPIC
- ☐ 69 STORM WATER POLLUTION PLAN SW3P
- ☐ 70 SW3P LAYOUT
- ☐ 71 VEGETATION SPEC

r = Revised Sheet

Total Sheets in Plan Set: 74