



Whitley & Siddons * (512)477-9491 * Fax (512)481-1983

www.WhitleySiddons.com

5/8/2019 WILLIAMSON 0320-03-100 SH 95 \$1,426,920|REHABILITATE BRIDGE

Sheet Title

- ☐ 1 TITLE SHEET
- ☐ 2 INDEX OF SHEETS
- ☐ 3 LOCATION MAP WILL_LOCATIONMAP
- ☐ 4 TYPICAL SECTIONS
- ☐ 5 GENERAL NOTES
- ☐ 5A GENERAL NOTES
- ☐ 5B GENERAL NOTES
- ☐ 5C GENERAL NOTES
- ☐ 5D GENERAL NOTES
- ☐ 5E GENERAL NOTES
- ☐ 6 ESTIMATE AND QUANTITY
- ☐ 6A ESTIMATE AND QUANTITY
- ☐ 7 QUANTITY SUMMARIES
- ☐ 8 QUANTITY SUMMARIES
- ☐ 9 TRAFFIC CONTROL PLAN NARRATIVE
- ☐ 10 TCP LAYOUT - SH 95 AT PECAN BRANCH - PHASE 3
- ☐ 11 TCP LAYOUT - FM 619 AT LITTLE DRY BRUSHY CREEK - PHASE 1
- ☐ 12 TCP LAYOUT - FM 619 AT LITTLE DRT BRUSHY CREEK - PHASE 2
- ☐ 13 CRASH CUSHION SUMMARY SHEET
- ☐ 14 BC1-14
- ☐ 15 BC2-14
- ☐ 16 BC3-14
- ☐ 17 BC4-14
- ☐ 18 BC5-14
- ☐ 19 BC6-14
- ☐ 20 BC7-14
- ☐ 21 BC8-14
- ☐ 22 BC9-14
- ☐ 23 BC10-14
- ☐ 24 BC11-14
- ☐ 25 BC12-14
- ☐ 26 TCP2-4-18
- ☐ 27 TCP2-8-18
- ☐ 28 TCP3-1-13
- ☐ 29 TCP3-2-13
- ☐ 30 TCP3-3-13
- ☐ 31 TCP7-1-18
- ☐ 32 WZBRK-13
- ☐ 33 WZSTPM-13
- ☐ 34 CSB1-10
- ☐ 35 CSB1-10
- ☐ 36 SSCB2-10
- ☐ 37 SSCB2-10
- ☐ 38 ACZ35-16
- ☐ 39 SLED-14
- ☐ 40 ROADWAY LAYOUT - FM 619
- ☐ 41 D & OM1-15
- ☐ 42 D & OM2-15
- ☐ 43 D & OMVIA-15
- ☐ 44 PM1-12
- ☐ 45 PM2-12
- ☐ 46 SH 95 PECAN BRANCH BRIDGE - BRIDGE REPAIRS
- ☐ 47 SH 95 PECAN BRANCH BRIDGE - BRIDGE REPAIRS
- ☐ 48 SH 95 PECAN BRANCH BRIDGE - BRIDGE REPAIRS
- ☐ 49 SH 95 PECAN BRANCH BRIDGE - BRIDGE REPAIRS
- ☐ 50 SH 95 PECAN BRANCH BRIDGE - BRIDGE REPAIRS
- ☐ 51 SH 95 PECAN BRANCH BRIDGE - BRIDGE REPAIRS
- ☐ 52 FM 619 LITTLE DRY BRUSHY CREEK BRIDGE -

Sheet Title

- ☐ BRIDGE REPAIRS
- ☐ 53 FM 619 LITTLE DRY BRUSHY CREEK BRIDGE - BRIDGE REPAIRS
- ☐ 54 FM 619 LITTLE DRY BRUSHY CREEK BRIDGE - BRIDGE REPAIRS
- ☐ 55 MISCELLANEOUS BRIDGE REPAIR DETAILS
- ☐ 56 MISCELLANEOUS BRIDGE REPAIR DETAILS
- ☐ 57 AJ
- ☐ 58 BEEJ
- ☐ 59 CRR
- ☐ 60 SRR
- ☐ 61 SRR
- ☐ 62 SW3P
- ☐ 63 EPIC
- ☐ 64 EC1-16
- ☐ 65 EC3-16

r = Revised Sheet

Total Sheets in Plan Set: 71