



Whitley & Siddons * (512)477-9491 * Fax (512)481-1983

www.WhitleySiddons.com

8/6/2019 EL PASO 2121-02-170 IH 10 \$1,987,505|PREVENTIVE MAINTENANCE

Sheet Title

- ☐ 1 TITLE SHEET
- ☐ 2 PROJECT LAYOUT
- ☐ 3 PROJECT LAYOUT
- ☐ 4 PROJECT LAYOUT
- ☐ 5 PROJECT LAYOUT
- ☐ 6 PROJECT LAYOUT
- ☐ 7 PROJECT LAYOUT
- ☐ 8 GENERAL NOTES
- ☐ **r** 8A GENERAL NOTES
- ☐ **r** 8B GENERAL NOTES
- ☐ **r** 8C GENERAL NOTES
- ☐ **r** 8D GENERAL NOTES
- ☐ **r** 9 ESTIMATE & QUANTITY
- ☐ **r** 10 QUANTITY SUMMARY
- ☐ **r** 11 TRAFFIC CONTROL PLAN LINE DIAGRAM
- ☐ 12 TCP TABLE SELECTION
- ☐ 13 BC1-14
- ☐ 14 BC2-14
- ☐ 15 BC3-14
- ☐ 16 BC4-14
- ☐ 17 BC5-14
- ☐ 18 BC6-14
- ☐ 19 BC7-14
- ☐ 20 BC8-14
- ☐ 21 BC9-14
- ☐ 22 BC10-14
- ☐ 23 BC11-14
- ☐ 24 BC12-14
- ☐ 25 TCP6-1-12
- ☐ 26 TCP6-2-12
- ☐ 27 TCP6-3-12
- ☐ 28 TCP6-4-12
- ☐ 29 WZBRK-13
- ☐ 30 SURVEY CONTROL LAYOUT 01
- ☐ 30A SURVEY CONTROL LAYOUT 02
- ☐ 30B SURVEY CONTROL LAYOUT 03
- ☐ 31 HORIZONTAL & VERTICAL CONTROL
- ☐ 32 RIPRAP TREATMENT 01
- ☐ 33 RIPRAP TREATMENT 02
- ☐ 34 RIPRAP TREATMENT 03
- ☐ 35 RIPRAP TREATMENT 04
- ☐ 36 RIPRAP TREATMENT 05
- ☐ 37 RIPRAP TREATMENT 06
- ☐ 38 RIPRAP TREATMENT 07
- ☐ 39 RIPRAP TREATMENT 08
- ☐ 40 RIPRAP TREATMENT 09
- ☐ 41 RIPRAP TREATMENT 10
- ☐ 42 RIPRAP TREATMENT 11
- ☐ 43 RIPRAP TREATMENT 12
- ☐ 44 RIPRAP TREATMENT 13
- ☐ 45 RIPRAP TREATMENT 14
- ☐ 46 RIPRAP TREATMENT 15
- ☐ 47 RIPRAP TREATMENT 16
- ☐ 48 RIPRAP TREATMENT 17
- ☐ 49 RIPRAP TREATMENT 18
- ☐ 50 RIPRAP TREATMENT 19
- ☐ 51 RIPRAP TREATMENT 20
- ☐ 52 RIPRAP TREATMENT 21
- ☐ 53 CRR1-19
- ☐ 54 SRR1-19 01

Sheet Title

- ☐ 55 SRR1-19 02
- ☐ 56 SWPPP LAYOUT 01
- ☐ 57 SWPPP LAYOUT 02
- ☐ 58 SWPPP LAYOUT 03
- ☐ 59 SWPPP LAYOUT 04
- ☐ 60 SWPPP LAYOUT 05
- ☐ 61 SWPPP LAYOUT 06
- ☐ 62 EPIC
- ☐ 63 EC1-16
- ☐ 64 EC3-16
- ☐ 65 EC9-16 01
- ☐ 66 EC9-16 02
- ☐ 67 EC9-16 03

r = Revised Sheet

Total Sheets in Plan Set: 73