

## Whitley & Siddons \* (512)477-9491 \* Fax (512)481-1983 www.WhitleySiddons.com

## 10/4/2017 HOUSTON 0117-06-049 SH 21 \$1,080,343|BRIDGE REPAIR

Sł	neet Title	Sheet Title
	1 TITLE SHEET	43 BRIDGE LAYOUT-BENT NO. 8 UNDERPINNING SH 7
	2 INDEX OF SHEETS INDEX	TRINITY RIVER BRIDGE
	3 GENERAL NOTES 3A GENERAL NOTES	44 EXISTING BRIDGE PLANS SH 7 TRINITY RIVER BRIDGE
r	4 ESTIMATE & QUANTITY SHEET	45 INTERIOR BENT NO. 8 UNDERPINNING SH 7
🗌 r	5 QUANTITY SUMMARY	TRINITY RIVER BRIDGE SHEET 1 OF 2
	6 BC 1-14 SHEET 1 OF 12 7 BC 2-14 SHEET 2 OF 12	46 INTERIOR BENT NO. 8 UNDERPINNING SH 7 TRINITY RIVER BRIDGE SHEET 2 OF 2
	8 BC 3-14 SHEET 3 OF 12	47 FD SHEET 1 OF 2
	9 BC 4-14 SHEET 4 OF 12	48 FD SHEET 2 OF 2
	10 BC 5-14 SHEET 5 OF 12	49 SWP3 INDEX
	11 BC 6-14 SHEET 6 OF 12 12 BC 7-14 SHEET 7 OF 12	50 EPIC SHEET 1 OF 2 51 EPIC SHEET 2 OF 2
	13 BC 8-14 SHEET 8 OF 12	
	14 BC 9-14 SHEET 9 OF 12	53 EC 3-16
	15 BC 10-14 SHEET 10 OF 12	
	16 BC 11-14 SHEET 11 OF 12 17 BC 12-14 SHEET 12 OF 12	
	18 TCP 1-2-12	
	19 TCP 2-2-12	
	20 TCP S-1-08A	
	21 TCP S-2-08A 22 WZ BRK-13	
	23 WZ RS-16	
	24 SH 21 WORKING AREA LAYOUT SHEET 1 OF 4 SH21	
	WORK AREA LAYOUT SHEET 1	
	25 SH 21 WORKING AREA LAYOUT SHEET 2 OF 4 SH21 WORK AREA LAYOUT SHEET 2	
	26 SH 21 WORKING AREA LAYOUT SHEET 3 OF 4 SH21	
	WORK AREA LAYOUT SHEET 3	
	27 SH 21 WORKING AREA LAYOUT SHEET 4 OF 4 SH21	
🗌 r	WORK AREA LAYOUT SHEET 4 28 SH 7 WORKING AREA LAYOUT	
	29 WF1-10	
	30 BRIDGE LAYOUT-BENTS 93, 94, 95, 98	
	UNDERPINNINGS SH 21 TRINITY RIVER BRIDGE SHEE	Ξ
	31 BRIDGE LAYOUT-BENTS 93, 94, 95, 98 UNDERPINNINGS SH 21 TRINITY RIVER BRIDGE SHEE	E
	32 EXISTING BRIDGE PLANS SH 21 TRINITY RIVER	
_	BRIDGE SHEET 1 OF 3	
	33 EXISTING BRIDGE PLANS SH 21 TRINITY RIVER BRIDGE SHEET 2 OF 3	
	34 EXISTING BRIDGE PLANS SH 21 TRINITY RIVER	
	BRIDGE SHEET 3 OF 3	
	35 INTERIOR BENT NO. 93 UNDERPINNING SH 21	
	TRINITY RIVER BRIDGE SHEET 1 OF 2 36 INTERIOR BENT NO. 93 UNDERPINNING SH 21	
	TRINITY RIVER BRIDGE SHEET 2 OF 2	
	37 INTERIOR BENT NO. 94 UNDERPINNING SH 21	
_	TRINITY RIVER BRIDGE SHEET 1 OF 2	
	38 INTERIOR BENT NO. 94 UNDERPINNING SH 21 TRINITY RIVER BRIDGE SHEET 2 OF 2	
	39 INTERIOR BENT NO. 95 UNDERPINNING SH 21	
	TRINITY RIVER BRIDGE SHEET 1 OF 2	
	40 INTERIOR BENT NO. 95 UNDERPINNING SH 21	
	TRINITY RIVER BRIDGE SHEET 2 OF 2 41 INTERIOR BENT NO. 98 UNDERPINNING SH 21	
	TRINITY RIVER BRIDGE SHEET 1 OF 2	
	42 INTERIOR BENT NO. 98 UNDERPINNING SH 21	
	TRINITY RIVER BRIDGE SHEET 2 OF 2	