



Whitley & Siddons * (512)477-9491 * Fax (512)481-1983

www.WhitleySiddons.com

5/8/2019 SAN PATRICIO 0180-10-083 SH 361 \$3,466,771|MILL AND INLAY

Sheet Title

- ☐ 1 TITLE SHEET
- ☐ 2 INDEX OF SHEETS
- ☐ 3 TYPICAL SECTIONS
- ☐ 4 TYPICAL SECTIONS
- ☐ 5 GENERAL NOTES
- ☐ 5A GENERAL NOTES
- ☐ 5B GENERAL NOTES
- ☐ 5C GENERAL NOTES
- ☐ 5D GENERAL NOTES
- ☐ 5E GENERAL NOTES
- ☐ 5F GENERAL NOTES
- ☐ 6 ESTIMATE AND QUANTITY
- ☐ 7 ROADWAY QUANTITIES
- ☐ 8 INTERSECTION QUANTITIES AND DETAILS
- ☐ 9 TURNOUT QUANTITIES AND DETAILS
- ☐ 10 SIGN QUANTITIES
- ☐ 11 SIGNS TO BE REMOVED
- ☐ 12 SUMMARY OF SMALL SIGNS
- ☐ 13 STRIPING QUANTITIES
- ☐ 14 SW3P SUMMARY
- ☐ 15 RAILROAD SCOPE OF WORK
- ☐ 16 RAILROAD REQUIRMENTS FOR NON-BRIDGE CONSTRUCTION PROJECTS
- ☐ 17 RAILROAD REQUIRMENTS FOR NON-BRIDGE CONSTRUCTION PROJECTS
- ☐ 18 SEQUENCE OF CONSTRUCTION
- ☐ 19 BC 1 - 14
- ☐ 20 BC 2 - 14
- ☐ 21 BC 3 - 14
- ☐ 22 BC 4 - 14
- ☐ 23 BC 5 - 14
- ☐ 24 BC 6 - 14
- ☐ 25 BC 7 - 14
- ☐ 26 BC 8 - 14
- ☐ 27 BC 9 - 14
- ☐ 28 BC 10 - 14
- ☐ 29 BC 11 - 14
- ☐ 30 BC 12 - 14
- ☐ 31 TCP 2-4 - 18
- ☐ 32 TCP 2-5 - 18
- ☐ 33 TCP 2-6 - 18
- ☐ 34 TCP 3-1 - 13
- ☐ 35 TCP 3-3 - 14
- ☐ 36 TCP 3-4 - 13
- ☐ 37 TCP 7-1 - 13
- ☐ 38 TCP S-3 - 08
- ☐ 39 WZ STPM - 13
- ☐ 40 WZ UL - 13
- ☐ 41 WZ RS - 16
- ☐ 42 HORIZONTAL ALIGNMENT DATA SHEET
- ☐ 43 FLEXIBLE PAVEMENT STRUCTURE REPAIR
- ☐ 44 SH 361 PAVEMENT REPAIR DETAIL
- ☐ 45 TE HMAC - 11
- ☐ 46 CRP - MH - WV - ADJ
- ☐ 47 TSR 3 - 13
- ☐ 48 TSR 4 - 13
- ☐ 49 TSR 5 - 13
- ☐ 50 SMD GEN - 08
- ☐ 51 SMD SLIP-1 - 08
- ☐ 52 SMD SLIP-2 - 08

Sheet Title

- ☐ 53 SMD SLIP-3 - 08
- ☐ 54 PM 1 - 12
- ☐ 55 PM 2 - 12
- ☐ 56 PM 3 - 12
- ☐ 57 STORMWATER POLLUTION PREVENTION PLAN SW3P
- ☐ 58 STORMWATER POLLUTION PREVENTION PLAN SW3P
- ☐ 59 ENVIRONMENTAL PERMITS, ISSUES AND COMMITMENTS
- ☐ 60 EC 9 - 16
- ☐ 61 EC 9 - 16
- ☐ 62 EC 9 - 16

r = Revised Sheet

Total Sheets in Plan Set: 68